UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,969,221 B2

Page 1 of 1

APPLICATION NO. : 10/716569

DATED

: November 29, 2005

INVENTOR(S) : Dennis Schultz

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 42, after "the external" insert --surface of the threaded insert. The depth of the dovetail slot is typically greater than the depth of the male threads on the external surface of the threaded insert .--.

Signed and Sealed this

Fifth day of September, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office